
Water Stress Indicator
Low
< 0.3
0.3 –0.4
0.4 –0.5
0.5 –0.6
0.6 –0.7
0.7 –0.8
0.8 –0.9
0.9 –1
High
>= 1
No discharge
Major River Basins